

#### Lecture 16 objectives are to use:

- Input capture to generate edge based interrupts;
- Input capture to measure period;
- Input capture to measure pulse width;

CCPx pins used for input capture: e.g., CCP0=PD4



#### See book section 8.1 Period Measurement

Select clock period,  $\Delta t$  because measurement resolution TIMER0\_TAILR\_R = 0xFFFF

## Choose edge (rise/fall) Arm interrupt on capture

# ISR

Poll to see which channel (if needed) Now = captured time Period = Now-Last Last = Now Acknowledge interrupt Save/process Period



Figure 6.1. Ping))) sensor signals. See PingDocs.pdf for an explanation of this figure.

- 1) make the **SIG** pin an output;
- 2) issue a 5  $\mu$ s output pulse;
- 3) switch the **SIG** pin to back to an input; and
- 4) measure the  $t_{IN}$ .

# Rising edge, record TAR

Falling edge, calculate t<sub>IN</sub>.

For HCSR04, skip steps 1,3



Use AddPeriodicThread to detect period too long (speed to slow)



Tachometer data collected with a 15-slot disk powered at +9V. IR sensor interface on left





What does this circuit do?



See two examples InputCapture\_4F120 count edges PeriodMeasure\_4F120 *16-bit period measurement*.

#### How to choose the resolution

Determine the minimum and maximum robot speed Convert speed to tachometer period

## For example

Period	7100	
	4	holes/rotation
P resolution	10	usec
Speed	3.521127	rps
Speed	211.2676	RPM



How to detect a speed too slow (period too large)?

Clear a counter on each tachometer edge Increment the counter on each rollover 0000 to FFFF If counter  $\geq 2$ , then wheel is stopped