
Problem: MSPM0 cannot be debugged

Observation: Device Manager shows "Stellaris Device Firmware Upgrade".




Solution: Find the xds100 folder. On my computer is at C:\ti\ccs2020\ccs\ccs_base\common\uscif\xds110



1) Run command line cmd.exe and execute these three lines

CD C:\ti\ccs2020\ccs\ccs_base\common\uscif\xds110 xdsdfu -b boot_loader.bin -r xdsdfu -f firmware 3.0.0.38.bin -r



2) Disconnect and re-connect the USB cable to host PC and confirm the XDS110 emulator port displayed in the device manager as shown below

